

DAFTAR GAMBAR

Gambar I.1 <i>Flow Chart</i> Produksi Twisting.....	14
Gambar I.2 Produksi Twisting	15
Gambar I.3 Kerusakan Subsistem Murata 310A Tahun 2015-2016.....	15
Gambar II.1 Klasifikasi Perawatan	20
Gambar II.2 Bath Tub Curve	24
Gambar II.3 Model LCC	32
Gambar II.4 Klasifikasi COUR.....	35
Gambar III.1 Model Konseptual	40
Gambar III.2 Sistematika Penulisan.....	41
Gambar IV.1 Hasil Uji Distribusi TBF Mesin Murata 310A	50
Gambar IV.2 Hasil Uji Distribusi TTR Mesin Murata 310A	52
Gambar IV.3 Hasil Uji TBF Distribusi Weibull	53
Gambar IV.4 Hasil Uji TTR Distribusi Weibull.....	54
Gambar V.1 Grafik Laju Kerusakan Mesin Murata 310A.....	73
Gambar V.2 Grafik <i>Annual Operating Cost</i>	74
Gambar V.3 Grafik <i>Annual Maintenance Cost</i>	74
Gambar V.4 Grafik <i>Shortage Cost</i>	75
Gambar V.5 Grafik <i>Sustaining Cost</i>	76
Gambar V.6 Grafik <i>Acquisition Cost</i>	76
Gambar V.7 Grafik <i>Total Life Cycle Cost</i>	77
Gambar V.8 Grafik <i>Failure Rate</i>	79
Gambar V.9 Grafik <i>Time Lost</i>	80
Gambar V.10 Grafik <i>Money Lost</i>	81