

DAFTAR GAMBAR

Gambar I. 1 Produksi Pupuk selama 5 tahun terakhir.....	1
Gambar I. 2 Gambar kerusakan sistem di Plan Ammonia 1A.....	2
Gambar I. 3 Data Frekuensi Kerusakan Mesin 1110 pada Tahun 2016-2017.....	4
Gambar II. 1 <i>Bath Tub Curve</i>	10
Gambar II. 2 Diagram Keputusan <i>Reliability Centered Maintenance</i> (RCM).....	21
Gambar II. 3 Diagram Keputusan <i>Reliability Centered Maintenance</i> (RCM) (Lanjutan).....	22
Gambar II. 4 P-F Interval.....	25
Gambar II. 5 Lembar Informasi <i>Reliability Centered Maintenance</i> (RCM).....	27
Gambar II. 6 Lembar Keputusan <i>Reliability Centered Maintenance</i> (RCM).....	28
Gambar II. 7 Model <i>Cost Of Unreliability</i> (COUR).....	29
Gambar III. 1 Model Konseptual.....	34
Gambar III. 2 Sistematisa Pemecahan Masalah.....	36
Gambar III. 3 Sistematisa Pemecahan Masalah (Lanjutan).....	37
Gambar V. 1 Hubungan <i>Number of failures</i> dengan MTTF.....	71
Gambar V. 2 <i>Corrective Lost Time</i>	72
Gambar V. 3 <i>Downtime Lost Time</i>	73