

DAFTAR GAMBAR

Gambar I.1 Jumlah Kerusakan Seluruh Mesin PT. PINDAD (PERSERO)	2
Gambar I.2 Jumlah Kerusakan Mesin CNC PT. PINDAD (PERSERO).....	3
Gambar II.1 Klasifikasi Perawatan	7
Gambar II.3 <i>Cost of Unreliability Model</i>	15
Gambar III.1 Model Konseptual	28
Gambar III.2 Sistematika Penyelesaian	30
Gambar III.5 Sistematika Penyelesaian Masalah (lanjutan)	32
Gambar IV.1 <i>System Breakdown Structure</i>	38
Gambar V.1 Hasil Identifikasi Model COPM.....	59
Gambar V.2 Grafik Hubungan <i>Number of Failure</i> dengan MTTF.....	60
Gambar V.3 Grafik <i>Corrective Time Lost</i>	61
Gambar V.3 Grafik <i>Downtime Lost Time</i>	62
Gambar V.5 Grafik <i>Corrective Money Lost</i>	64
Gambar V.6 Grafik <i>Downtime Money Lost</i>	65
Gambar L.A 1. MESIN HURON.....	72
Gambar L.A2 Subsistem Head.....	73
Gambar L.A3. Subsistem Monitor	74
Gambar L.A4 Subsistem Electricity	75
Gambar L.D1 Uji Anderson Darling TTF Head	86
Gambar L.D1. Uji Anderson Darling TTR Head.....	87
Gambar L.D3. Uji Anderson Darling DT Head.....	88
Gambar L.D4. Uji Anderson Darling TTF Monitor	89
Gambar L.D5. Uji Anderson Darling TTR Monitor	90
Gambar L.D6. Uji Anderson Darling DT Monitor	91
Gambar L.E1. <i>Plotting</i> Distribusi MTTF Head	92

Gambar L.E2. <i>Plotting</i> Distribusi MTTR Head.....	93
Gambar L.E3. <i>Plotting</i> Distribusi MDT Head.....	94
Gambar L.E4. <i>Plotting</i> Distribusi MTTF Monitor	95
Gambar L.E5. <i>Plotting</i> Distribusi MTTR Monitor	96
Gambar L.E6. <i>Plotting</i> Distribusi MDT Monitor	97