

DAFTAR GAMBAR

| | |
|---|----|
| Gambar I.1 Produk Jala Ikan..... | 1 |
| Gambar I.2 Alur Proses di Departemen Netting | 2 |
| Gambar I.3 Defect Single..... | 5 |
| Gambar I.4 Fishbone Diagram Defect Single | 5 |
| Gambar I.5 Part Hikikagi Turun..... | 6 |
| Gambar I.6 Part Kyo-Jobang Kasar | 7 |
| Gambar II.1 Fishbone Diagram | 13 |
| Gambar II.2 Tahapan Reverse Engineering | 19 |
| Gambar IV.1 Mesin Netting Eksisting..... | 29 |
| Gambar IV.2 Kondisi Hikikagi Seharusnya..... | 30 |
| Gambar IV.3 Kondisi Hikikagi Bermasalah | 30 |
| Gambar IV.4 Rancangan Mesin <i>Netting</i> Eksisting | 35 |
| Gambar IV.5 Hasil Rancangan Usulan Perbaikan | 40 |
| Gambar IV.6 Flowchart Rancangan Usulan Perbaikan | 41 |
| Gambar V.1 Sensor Limit Switch..... | 43 |
| Gambar V.2 Arduino Atmega2560 | 44 |
| Gambar V.3 Buzzer | 45 |
| Gambar V.4 Lampu Indikator | 45 |