LIST OF TABLES

Table I.1 The Definition of Beans Type's Defect.....14
Table I.2 Prevention That Has Been Done By The Company.....15
Table II.1 Dual Meaning of Six Sigma.....19
Table II.2 Stability and Process Capability.....24
Table II.3 Relations and Sigma DPMO.....25
Table II.4 Some enefits of Achieving The Sigma Level.....26
Table II.5 Value Severity FMEA.....32
Table II.6 Value of Occurence FMEA.....33
Table II.7 Value Detection FMEA.....34
Table II.8 Comparison Reserach With Othere Research Resources.....36
Table II.9 Comparison of Six Sigma Methods with Other Method.....37
Table IV.1 Total Delivery Beans From Collector to PT. Abo Farm Data in January – December 2012.....49
Table IV.2 Total Delivery Beans Data to PT. Abo Farm Period of January – December 2012.....50
Table IV.3 Types of Defect for Beans.....51
Table IV.4 Bean's CTQ and Potential CTQ.....52
Table IV.5 Defect Type Illustration.....52
Table IV.6 Stability Process Calculation of Beans Delivery Process From Collecting Area.....56
Table IV.7 Summary Value Calculation's Result of DPMO and Sigma Value by Using Sigma Calculator.....59
Table IV.8 Defect Types Which is Categorized as Broken Beans Data.....60
Table IV.9 5 Why's Table for The Cause of The Stems of Beans Asunder Man Power Factor (1).....62
Table IV.10 5 Why's Table for The Cause of The Stems of Beans Asunder Man Power Factor (2).....63
Table IV.11 5 Why's Table for The Cause of The Stems of Beans Asunder.....63
Table IV.12 5 Why's Analysis Table Cause Of No Short-Sighted in Beans Defects Man Power Factor.....65
Table IV.13 5 Why's Analysis Table Cause Defects No Short-Sighted in Beans 66
Table IV.14 Table 5 Why's Analysis pf Rev's Cause of Disability Existence Nails Scratches on Surface beans Man Power Factor (1).....67
Table IV.15 5 Why's Analysis Table of Rev's Cause of Disability Existence Nails Scratches on Surface Beans Man Power Factor (2).....68
Table IV.16 5 Why's Analysis Table of Rev's Cause of Disability Existence Nails Scracthes on Surface Beans Man Power Factor (3).....68
Table IV.17 5 Why's Analysis of Rev's Cause of Disability Existence Nails Scratches on Surface Beans.....69

Table IV.18 RPN Value Calculation Results.....72
Table IV.19 Order RPN Results 73
Table IV.20 Kipling Method.....**Error! Bookmark not defined.**
Table IV.21 Proposed Improvements 79
Table IV.22 Analysis of Proposed Repair Default Setting Maximum Weight Operators 80
Table IV.23 Table Product Specifications Platform Handtruck Plastic KW 05-415/ KW 0500415 84
Table IV.24 Analysis of Proposed Improvements "Setting an Ergonomic Compartment Size" 94
Table IV.25 Anthropometric Data For Size Shoulder Width (LB), Eye Height Stand (TMB) and High Elbow Stand (TSB) Lifting operator PT. Abo Farm. 95
Table IV.26 Size Ergonomics Compartment Width Suggestions When Referring At 2 (Two) Beans the Aligned 97
Table IV.27 Size Ergonomics Compartment Width Suggestions When Referring On 3 (Three) Beans the Aligned 98
Table V.1Alternative Solutions to reduce severe congenital roots of the operator at the time of lifting.....105
Table V.2 Strengths and Weaknesses of Alternative Solutions to Reduce Weight roots of Congenital Operator at the time of the Rapture.....106
Table V.3 Alternative Solutions to the Root Problem How improper lifting compartment.....107
Table V.4 Strengths and Weaknesses of Alternative Solutions on How to Root Problem compartment improper lifting.....108
Table V.5 Alternative Solutions to the Root Problem Compartment size (length) is large.....112
Table V.6 Strengths and Weaknesses of Alternative Solutions to the roots of a large compartment size 112
Table V.7 Proposed Additions Parts Quality Control (QC) at PT. Abo Farm.....115
Table V.8 Alternative Solutions to the Root Problem Absence Harvesting Training.....116
Table V.9 Strengths and Weaknesses of Alternative Solutions to the Root Problem Absence Harvesting Training.....117