

Abstract

Library 400 in Cirebon has increased with the number of visitors from the previous year, an increase of 0.92% around 20,409 people each year. Then, from that problem the society in Cirebon experienced an increase in reading interest in the library, according to the Head of Library Material Processing and Preservation Service, said the number of facilities such as reading rooms and supporting facilities will continue to be optimized. But the fact is, the library 400 in Cirebon is still not optimizing facilities and supporting facilities, such as zoning and irregular space blocking, so there is no separation between noisy areas and quiet areas that have an impact on visitor comfort. Many empty rooms have not been properly utilized. Also, there are rooms in the library that are under standards, such as some of the facilities in the library that are incomplete, other than that the atmosphere of the library is monotonous and unrepresentative, the air and room lighting are not good. So, it is necessary to have a redesign for Library 400 in Cirebon city that can meet the standard facilities in the library, create a new atmosphere, be able to attract the interest of the society of Cirebon to come to the library with the aim to improve the quality of reading that can add to scientific insights and creativity so that living standards become better.

Keywords: Redesign, Library 400 in Cirebon, Facility Standards