

DAFTAR GAMBAR

| | |
|--|----|
| Gambar I.1. 1 Grafik Perbandingan Persentase Defect dengan Persentase Toleransi Produk Defect..... | 3 |
| Gambar I.1. 2 Alur Proses Produksi Sparepart Adjuster Comp Chain Type K45 | 4 |
| Gambar I.1. 3 Diagram Pareto Defective pada PT. XYZ..... | 9 |
| Gambar I.1. 4 Diagram Fishbone..... | 10 |
| Gambar II.10. 1 FMEA worksheet..... | 31 |
| Gambar II.5. 1 CTQ (Critical To Quality) Tree..... | 20 |
| Gambar II.7.1. 1 Control Chart..... | 22 |
| Gambar II.7.1. 2 Summary of different types of control charts..... | 22 |
| Gambar II.7.2. 1 Sigma Rating and DPMO..... | 25 |
| Gambar II.9. 1 Digram Sebab dan Akibat/Fishbone..... | 27 |
| Gambar IV.2.2. 1 Alat Bantu Penopang di dalam Dies..... | 44 |
| Gambar IV.2.2. 2 Alat Bantu Penopang..... | 45 |
| Gambar IV.2.2. 3 Strees Simulation Alat Bantu Penopang..... | 46 |
| Gambar IV.2.3. 1 Usulan Display untuk Ketentuan Pelat pada Dies | 48 |