

DAFTAR SIMBOL

Simbol/Notasi	Deskripsi	Halaman pertama kali digunakan
OEE	<i>Overall Equipment Effectiveness</i>	11
ORE	<i>Overall Resource Effectiveness</i>	11
TPM	<i>Total Productive Maintenance</i>	11
A	<i>Availability</i>	15
P	<i>Performance Efficiency</i>	16
Q	<i>Quality Rate</i>	18
Ot	<i>Operation Time</i>	18
Ra	<i>Required Availability</i>	18
D	<i>Downtime</i>	6
Ct	<i>Cycle Time</i>	19
T	Total Produksi	19
Bl	<i>Breakdown Losses</i>	19
Bt	<i>Breakdown Time</i>	20
Lt	<i>Loading Time</i>	20
S	<i>Set-up and Adjustment Losses</i>	20
St	<i>Set-up Time</i>	20
Im	<i>Idling and Minor Stoppage</i>	20
Tn	<i>Total Non-productive Time</i>	20
Rs	<i>Reduced Speed Losses</i>	21
Rl	<i>Re-work Losses</i>	21

Simbol/Notasi	Deskripsi	Halaman pertama kali digunakan
Td	Total <i>Defect</i> Produksi	21
Ry	<i>Reduced Yield Losses</i>	22
Rp	<i>Rejected Product</i>	22
Pp	<i>Planned Production Time</i>	23
Tt	<i>Total Time</i>	23
R	<i>Readiness</i>	22
Ar	<i>Availability of Facility</i>	22
C	<i>Changeover Efficiency</i>	24
Am	<i>Availability of Material</i>	22
Rt	<i>Running Time</i>	24
Amp	<i>Availability of Manpower</i>	22
Art	<i>Actual Running Time</i>	25
Et	<i>Earned Time</i>	25
U	<i>Unit</i>	25
Qp	<i>Quality Produced</i>	25
Qoa	<i>Quality of Parts Accepted</i>	25
Qop	<i>Quality of Parts Produced</i>	25