

## DAFTAR GAMBAR

|                                                                                       |    |
|---------------------------------------------------------------------------------------|----|
| Gambar I.1 Jenis – Jenis <i>Defect</i> Kain TR 62 .....                               | 3  |
| Gambar II.1 <i>Value Stream Mapping</i> .....                                         | 11 |
| Gambar II.2 <i>Fishbone Diagram</i> .....                                             | 17 |
| Gambar II.3 Diagram Blok PID <i>Controller</i> .....                                  | 19 |
| Gambar II.4 Grafik <i>Overshoot</i> dan <i>Undershoot</i> PID .....                   | 19 |
| Gambar II.5 Diagram Konseptual Aplikasi PLC .....                                     | 20 |
| Gambar III.1 Model Konseptual .....                                                   | 23 |
| Gambar III.2 Sistematika Pemecahan Masalah .....                                      | 25 |
| Gambar IV.1 Kain <i>Greige</i> .....                                                  | 30 |
| Gambar IV.2 <i>Operation Process Chart</i> Pencelupan Kain TR 62 .....                | 32 |
| Gambar IV.3 Kain <i>Greige</i> yang telah dipindahkan dari gudang <i>Greige</i> ..... | 33 |
| Gambar IV.4 Proses Bakar Bulu ( <i>Pre-Treatment</i> ) .....                          | 34 |
| Gambar IV.5 Proses <i>Scouring</i> .....                                              | 34 |
| Gambar IV.6 Proses <i>Setting</i> .....                                               | 35 |
| Gambar IV.7 Proses <i>Thermosol Dyeing</i> .....                                      | 35 |
| Gambar IV.8 Proses <i>Reduction Clearing</i> (RC) .....                               | 36 |
| Gambar IV.9 Proses <i>Cold Pad Batch Dyeing</i> .....                                 | 37 |
| Gambar IV.10 Proses <i>Washing/Soaping</i> .....                                      | 38 |
| Gambar IV.11 <i>Value Stream Mapping Current State</i> .....                          | 44 |

|                                                                                        |    |
|----------------------------------------------------------------------------------------|----|
| Gambar IV.12 Persentase <i>Defect Rate</i> Kain Motif TR 62 Bulan Maret 2017           |    |
| Stasiun Kerja Celup <i>Disperse</i> .....                                              | 48 |
| Gambar IV.13 <i>Fishbone Diagram</i> Permasalahan <i>Defect</i> Warna Tidak Standar .. | 50 |
| Gambar IV.14 Bagan Sistem Kontrol Kestabilan Suhu .....                                | 55 |
| Gambar IV.15 Ilustrasi Sistem Kontrol Kestabilan Suhu .....                            | 56 |
| Gambar IV.16 <i>Flowchart</i> Kerja Sistem .....                                       | 57 |
| Gambar IV.17 <i>Ladder Diagram</i> .....                                               | 58 |
| Gambar IV.18 Kartu Kontrol Pengecekan dan Kebersihan Radiator .....                    | 60 |
| Gambar IV.19 Desain Alat Bantu Wadah Pelarutan Warna .....                             | 61 |
| Gambar IV.20 <i>Value Stream Mapping Future State</i> .....                            | 63 |
| Gambar V.1 <i>Watch Table</i> Hasil Simulasi pada PLC Simulation .....                 | 64 |
| Gambar V.2 Grafik <i>Overshoot</i> dan <i>Undershoot</i> PID .....                     | 65 |