

LIST OF FIGURES

Figure I.1 Taguchi and conventional loss functions	3
Figure I.2 S530 X 1000 Lathe in Manufacturing Building at Telkom University..	4
Figure II.1 Taguchi Design Procedure (Zhang et al., 2007)	8
Figure II.2 Auxiliary diagrams for determination of values of a) Ra and b) Rz (Burakowski and Wierzchoń, 1999)	19
Figure II.3 Turning Operation (Groover, 2010).....	21
Figure II.4 Basics of the turning process normally done on a lathe (Black and Kohser, 2008).....	22
Figure II.5 Bench Lathe Machine (Singh, 2006)	22
Figure III.1 Conceptual Model.....	26
Figure III.2 Problem Solving Systematics	27
Figure III.2 Problem Solving Systematics (Continue).....	28
Figure III.3 Surface Roughness Measurement.....	33
Figure IV.1 Workpiece Size details	37
Figure IV.2 Workpiece Object.....	37
Figure IV.3 C45 Steel Round Bar	38
Figure IV.4 Mitutoyo SJ-410 Series	38
Figure IV.5 S530 X 1000 Winho High-Speed Precision Lathe	39
Figure IV.6 Insert Tools Walter VBMT160408-MM4 WSM20S	40
Figure IV.7 Product Drawing.....	40
Figure IV.8 Machining Process	41
Figure IV.9 Put the raw material (C45 Steel) into the Spindle	42
Figure IV.10 Facing process	42
Figure IV.11 Mark off the center of material in the front face of the tailstock	43
Figure IV.12 Turning process	43
Figure IV.13 Cut the material into a specific size.....	43
Figure IV.14 Cut objects that have been processed with a hacksaw	44
Figure IV.15 C45 Steel part	44
Figure IV.16 Cutting Parameters on S530 X 1000 Lathe	45
Figure IV.17 Cutting process and parts that have been cut.....	46
Figure IV.18 Main Effects Plot for SN Ratios.....	50

Figure IV.19 Probability Plot of Spindle Speed	51
Figure IV.20 Probability Plot of Feed Rate	52
Figure IV.21 Probability Plot of Depth of Cut.....	53
Figure IV.22 Interval Plot of SNRA1 vs Feed Rate.....	55
Figure IV.23 Interval Plot of SNRA1 vs Depth of Cut.....	56
Figure IV.24 Differences of Means for Spindle Speed, Feed Rate, and Depth of Cut.....	57
Figure IV.25 Differences of Means for SNRA1 (Spindle Speed)	58
Figure IV.26 Differences of Means for SNRA1 (Feed Rate)	60
Figure IV.27 Differences of Means for SNRA1 (Depth of Cut).....	61