LIST OF TERM

Description	First page that used
The highest value from the	
multiplication of the Severity,	3
Occurance, Detection values	
shows that this risk is a priority	
that will be prioritized.	
The left over plate is the result	18
of cutting theframe, car body	
he container for the primary	18
gas ionization process by	
tungsten electrodes which will	
be flowed through the nozzle,	
which can put out fire	
he machine used to cut metal	
The working principle of	18
plasma cutting is to flow an	
electric current in the gas that	
passes through a small cross	
section so that it will heat the	
air to a very high temperature	
which is called the plasma	
phase	
	The highest value from the multiplication of the Severity, Occurance, Detection values shows that this risk is a priority that will be prioritized. The left over plate is the result of cutting theframe, car body he container for the primary gas ionization process by tungsten electrodes which will be flowed through the nozzle, which can put out fire he machine used to cut metal The working principle of plasma cutting is to flow an electric current in the gas that passes through a small cross section so that it will heat the air to a very high temperature which is called the plasma