

ABSTRACT

A Mosque is a place for muslims to pray first established by The Prophet Muhammad SAW. Beside a place for praying mosque also has a role and function which support the religion activity. Surely the facility inside the mosque is not only a prayer room but also a supporting room like DKM office, library, all purpose room and another room which is need to be noticed especially the facility inside the room according to the standarization. The Al Ukhuwwah Great Mosque which located in Jalan Wastukencana number 27, Babakan Ciamis, Sumur Bandung, Bandung City which classified as distric or city mosque. There are exsisting problem obtained from the survey, interview and documentation also analized with literature. Observed by the site, the mosque is surrounded by buildings and streets that caused pollution from the vehicles like sounds and air pollution that affect the mosque area. That problem have a bad impact to the health and amenities of the user. Incompatibility of the room function with the exsisting facilities and the standarization become a main problem in Al Ukhuwwah great mosque. The supporting room at the mosque caused the room organization needs to be nicely arranged and in accordance with users circulation and activity. The mosque categorized as public space which have to facilite the users well especially in praying activity.