

DAFTAR GAMBAR

Gambar I. 1 <i>Air Brake System</i>	1
Gambar I. 2 Diagram pareto jenis <i>defect</i> komponen <i>Coupling Head</i> tahun 2018..	3
Gambar I. 3 Diagram <i>Fishbone</i>	8
Gambar II. 1 Contoh <i>critical to quality tree</i>	16
Gambar II. 2 Contoh diagram <i>cause and effect</i>	25
Gambar II. 3 Ilustrasi 5 <i>Why's</i>	27
Gambar III. 1 Model Konseptual	34
Gambar III. 2 Sistematika Pemecahan Masalah	36
Gambar IV. 1 Poster.....	45
Gambar IV. 2 Alat bantu dudukan <i>Coupling Head</i>	47
Gambar IV. 3 Gambar teknik dudukan <i>Coupling Head</i>	48
Gambar IV. 4 <i>Stress</i> dudukan <i>Coupling Head</i>	49
Gambar IV. 5 <i>Strain</i> dudukan <i>Coupling Head</i>	49
Gambar IV. 6 Deformasi dudukan <i>Coupling Head</i>	49
Gambar V. 1 Alat bantu dudukan komponen <i>Coupling Head</i>	53