

DAFTAR GAMBAR

Gambar I.1 Proses Produksi <i>Cover On-Off</i>	1
Gambar I.2 Data Frekuensi Kerusakan Mesin PT XYZ 2016-2018.....	2
Gambar I.3 Data Produksi Mesin PL1250 Tahun 2017-2018.....	2
Gambar II.1 Klasifikasi <i>Maintenance</i>	8
Gambar II.2 Model <i>Overall Resource Effectiveness (ORE)</i>	12
Gambar III.1 Model Konseptual	24
Gambar III.2 Sistematisa Pemecahan Masalah	26
Gambar III.3 Sistematisa Pemecahan Masalah (Lanjutan 1).....	27
Gambar III.4 Sistematisa Pemecahan Masalah (Lanjutan 2).....	28
Gambar V.1 Grafik <i>Availability Rate</i>	56
Gambar V.2 Grafik <i>Performance Efficiency</i>	56
Gambar V.3 Grafik <i>Quality Rate</i>	57
Gambar V.4 Grafik <i>Readiness</i>	59
Gambar V.6 Grafik <i>Changeover Efficiency</i>	60
Gambar V.7 Grafik <i>Availability of Material</i>	61
Gambar V.11 Grafik Perbandingan OEE dan ORE	62
Gambar V.10 Diagram Pareto <i>Six Big Losses</i>	63
Gambar V.11 Diagram <i>Fishbone Reduced Speed Loss</i>	65
Gambar V.12 Diagram <i>Fishbone Idling and Minor Stoppages Loss</i>	66