

## DAFTAR GAMBAR

Gambar I.1 Kerusakan Mesin C1110 Tahun 2016 s/d 2019 .....	1
Gambar I.2 <i>Downtime</i> Mesin C1110-JC Tahun 2016 s/d 2019 .....	2
Gambar I.3 Proses Produksi Sistem <i>Benfield</i> .....	2
Gambar I.4 Pompa Sentrifugal Horizontal .....	4
Gambar II.1 <i>Bathtub Curve</i> .....	8
Gambar II.2 Tipikal <i>Risk Matrix</i> .....	11
Gambar II.3 Simbol <i>Fault Tree</i> .....	16
Gambar II.4 Keterangan Simbol <i>Fault Tree</i> .....	16
Gambar II.5 Interval P-F .....	17
Gambar III.1 Model Konseptual .....	19
Gambar III.2 Sistematisa Pemecahan Masalah .....	21
Gambar III.3 Sistematisa Pemecahan Masalah (lanjutan) .....	22
Gambar IV.1 <i>System Breakdown Structure</i> Mesin C1110 .....	25
Gambar IV.2 Komponen Mesin C1110 .....	25
Gambar IV.3 <i>Bearing</i> .....	27
Gambar IV.4 <i>Pump Impeller + Shaft (Rotor)</i> .....	27
Gambar IV.5 <i>Mechanical Seal</i> .....	27