

DAFTAR GAMBAR

Gambar 1.1	Grafik Jumlah Produk Rusak dalam Gudang Retur Tahun 2023	2
Gambar 1.2	Grafik Kecacatan Produk Periode Januari - Desember 2023	4
Gambar 3.1	Diagram Alur Penelitian	29
Gambar 4.1	Logo PT NBM	32
Gambar 4.2	Peta Lokasi PT NBM.....	33
Gambar 4.3	Struktur Organisasi Divisi Gudang.....	34
Gambar 4.4	Alur Proses Bisnis	39
Gambar 4.5	<i>Defect</i> Patah.....	41
Gambar 4.6	<i>Defect</i> Retak.....	42
Gambar 4.7	<i>Defect</i> Gompal	43
Gambar 4.8	<i>Defect</i> Rimpil.....	43
Gambar 4.9	<i>Defect</i> Sobek.....	44
Gambar 4.10	<i>Defect</i> Bergelombang	44
Gambar 4.11	Diagram Pareto Jenis <i>Defect</i>	46
Gambar 4.12	<i>P-Chart</i> Jumlah <i>Defect</i>	49
Gambar 4.13	Diagram <i>Fishbone</i> Jenis <i>Defect</i> Retak.....	50
Gambar 4.14	Diagram <i>Fishbone</i> Jenis <i>Defect</i> Gompal	51
Gambar 4.15a	Form Pemeriksaan <i>Forklift</i>	65
Gambar 4.15b	Form Pemeriksaan <i>Forklift</i>	66
Gambar 4.16	<i>Paperboard</i> Corner Protection.....	67
Gambar 4.17	<i>Foam</i> Corner Protection.....	68
Gambar 4.18	Kombinasi Corner Protection	68